

H.C.B-C1490 SCANIA 113 (10 SPEED) TRANSMISSION MAINSHAFT/ SIDE SHAFT/ INPUT SHAFT BEARING REMOVAL/ INSTALLATION TOOL



* Formerly, engineers extract the bearings by damaging the bearing. It might damage the part and the shaft. Use this tool can extract the five bearings easily and no damage the parts. * The best tool for removing SCANIA 113 transmission bearing. * Easy

Rating: Not Rated Yet

Price:

Sales price:

Discount:

[Ask a question about this product](#)

Manufacturer: [HCB Specialty Tools](#)

Description



STEP 1

STEP 2

Page 1 of 2

Page 1 of 2

Page 1 of 2



Extraction of the input shaft bearings:



Installation of the input shaft bearings: